

R3 - Group 364

Remote Control Central Door Lock, Programming

1

Note: This step should be completed within a 15 second time frame.

2

Note: The instrument cluster does not indicate programming mode.

3

Note: It is recommended that at least one remote control to be secured at all times, to avoid the replacement of the module-remote control pair, if both original remote controls are missing.

Note: This step is a security feature.

4

Note: No reprogramming is possible without an original remote control.

5

6

7

8

Note: Due to the security feature, all desired remote controls to be programmed must be programmed, before the programming mode is exited into the Normal mode. To add a new remote control and keep the previous ones, all steps must be taken again having all the controls ready. The module starts each programming process anew.